


PROBLEM SET

Program 1


ALL SLOTS TO BE .200 DP.
 CLEARANCE TO BE .050 ABOVE TOP OF PART
 FEED RATE TO BE 15 I.P.M.



<u>ORIGIN</u>	Loc.	X CO'ORD.	Y CO'ORD
	START	-4.000	2.500
	1.	.000	1.750
	2.	1.250	1.750
	3.	2.250	1.750
	4.	3.250	1.750
	5.	3.250	.750
	6.	2.000	.500
	7.	.750	.500
	8.	2.250	.000
	9.	.000	.000
	10.	.000	1.000

Program 2

DRILLING




LOC.	X CO'ORD.	Y CO'ORD.
START	-1.000	2.000
1.	1.000	- .500
2.	1.000	-1.250
3.	2.250	-1.250
4.	4.000	-1.500
5.	2.750	-2.500
6.	.500	-2.250

FEEED RATE TO BE 8 IPM
 CLEARANCE TO BE .05 ABOVE TOP OF
 PART

Program 3


DRILLING



LOC	X CO'ORD	Y CO'ORD
START	.000	2.000
1.	1.250	-.750
2.	2.000	.000
3.	3.000	.000
4.	3.500	-1.250
TOOL CHG.	3.000	2.000
5.	3.000	-1.750
6.	2.500	-2.250
7.	.500	-2.000


Program 4

MILL & DRILL




Program 6

Sim 4




NOTE: PROGRAM CUTTER ON THE LINE...

Program 7



Program 7

Multi-Quadrant Circular




1. Cutter on line go from A to D
(X0,Y0) center of Arc.
2. .5" Dia. end mill cut outside
of line B to G
(X0,Y0) center of Arc.

Speed & Feed for above:

1800 RPM
Plunge 7.5 IPM, Mill 15 IPM

Tool Change Position: X-3, Y0

Depth of Cut: .100



3. .5" Dia. end mill cut inside
of line G to D
(X0,Y0) on line at "F".
4. 1" Dia. end mill cut inside
of line E to A
(X0,Y0) on line at "F".



Speed & Feed for above:

1450 RPM
Plunge 6.0 IPM, Mill 12. IPM

Tool Change Position: X-3, Y0

Depth of Cut: .100

Program 9



Program 9

Instructions:


Material 1/2 X 4." Sq. 2024 Aluminum
 Top Surface of Part = "Z" Zero
 Chamfer all Holes .025/side

Tooling:

Tool#	Description	RPM	Feedrate	Tool Chg. Loc.
1	.5 Dia End Mill	1270	12. IPM	Start Loc.
2	.5 Dia 90° Spot Drill	1500	8.	T.C.#1 Pos.
3	.437 Dia. Drill	1450	8.	T.C.#2
4	.4505 Dia. Reamer	500	5.	T.C.#2
5	.25 Dia. End Mill	3120	12.	T.C.#2
6	.209 Dia. Drill	3300	8.	T.C.#1
7	1/4-20 Unc Tap	200	9.9	T.C.#1

Tool Change Pos. #1 = X3.75 Y-6.75

Tool Change Pos. #2 = X-.25 Y-6.75



Program 10


LOOPING

Tool #1 .5 Dia 90° Spot Drill 1500 RPM 8. IPM


Tool #2 .25 Dia Drill 3300 RPM 9. IPM

Note: Top of part = "Z" Zero

Tool Change Position X-4. Y3.



Program 11



Programming Instructions:

"Z" Zero = Top of the Part
Use G75 Circular

Tooling- .25Dia. End Mill 3300 RPM

Plunge Feed 5. IPM -- .1 Deep ; Contour Mill 10. IPM