


UNIVERSAL INDICATING ATTACHMENTS

Precision set-ups with speed and accuracy demanded by modern machine work, is now possible by using one or another of these interchangeable attachments with this Wiggler. You can indicate from toolmakers' gages or holes, ground surfaces, gauge blocks, the side of round work, and true to layout lines. The bent shaft holds indicators of all types, and allows the ball of the indicator to be positioned on the spindle center.

How to use the BALL SHAFT




PRECISION BALL the ball applied to surfaces is hardened and ground to an exact diameter of .250". In making measurements, taking half its diameter, or .125", gives a precise center.

Indicating from ground or machined surfaces, gauge blocks, etc.

The ball shaft is used for set-ups where locations are to be made from ground or machined surfaces, gauge blocks, or sides of round work. This attachment is the one you will use most frequently, as you will find that it simplifies many difficult indicating problems. DISC CONTACT POINT (100") permits use in more confined areas, such as slots, holes, etc.



Bent shaft holds ALL INDICATORS



This indicator shaft is used with an indicator to locate from tool.


STEP 1

Insert the large ball of attachment into spring chuck. Make the ball run true by holding any blunt object against it. Apply a thin coating of layout blue on the ball and feed the work up to it until the blue is barely wiped.




STEP 2

Lower the table and move it .125" (half the diameter of the ball) to bring the reference surface (S) directly under the spindle center. By using the millerometer collar on the lead screw, any desired distance from the original position can then be located.




Locating TRUE vertical center lines of round bars



STEP 1 Apply layout blue to the upper surface of the work. Then, with the ball shaft running, true false the table gradually while moving it slightly back and forth until the blue is barely wiped by the precision ball. This locates the height of the upper surface of the work.



STEP 2 Next, with spindle running, move the work away from the spindle and raise it a distance of one-half the known diameter of the work plus .125" (one-half the diameter of the precision ball). This places the center line of the ball and of the work in the same horizontal plane. Give the ball and move the work toward it until the blue is barely wiped. This gives you the location of the side of the work.




STEP 3 Now you can locate the spindle center precisely above the vertical center line of the work by lowering the table and moving it toward the spindle one-half the diameter of the work plus .125" (one-half the diameter of the precision ball.)





The sharp, slender point is used to find center and for truing to layout lines. It insures accuracy and is readily replaceable. The "Needle-Point" is held in a rigid friction grip. To replace with new point, merely use pliers. Grinding is needed — the shaft retains its original length. It is the same precision point used on other "Needle-Point" tools.

Shafts snap into the Spring Chuck


Knurled Collar Adjusts the Chuck Spring Tension and Maintains Adjustment
ALWAYS LOOSEN KNURLED CHUCK NUT OR COLLAR BEFORE INSERTING OR REMOVING THE SHAFT ATTACHMENTS
Various attachments may be interchanged without removing the wiggler.
Balls and body are hardened.




Interchange shafts this quick, easy way



No. S-389-3
WIGGLER
SET WITH
Needle Point,
Ball Point,
and Indicator
Holder in
snap-in
Viny Case.
Packed 1 set
to a box.
Weight:
3 ounces.



No. S-389-4
WIGGLER
SET WITH
Needle Point,
Ball Point,
Disc Point,
and Indicator
Holder in
snap-in
Viny Case.
Packed 1 set
to a box.
Weight:
4 ounces.



how to use the



Universal