

This is meant to illustrate the problem with the contour milling.

The first pass was a A. The tool then moved over and down to B and cut a pass. Then, at the same depth the tool cut air a B1, B2, B3 and so on.

Lots of wasted time. To do the shorter edges I hand wrote a program that eliminated all the empty passes and saved a lot of time.

