

PRELIMINARY COPY
FOR REFERENCE ONLY

PROGRAMMING MANUAL
ELLIS TECH
FOR THE

R2E3 SERIES I, CNC
MILLING, DRILLING & BORING MACHINE

4-17
2-6

MAY, 1983



Bridgeport Machines Division of Textron Inc.

11040532
REV 0 5/83

TABLE OF CONTENTS

CHAPTER 1		SPECIFICATION FOR THE BRIDGEPORT E-CNC
1.1	GENERAL	1-1
1.2	MACHINE DESCRIPTION	1-2
CHAPTER 2		SPECIFICATIONS
2.1	SPECIFICATION	2-1
CHAPTER 3		PROGRAMMING FORMAT
3.1	OVERVIEW	3-1
3.2	PART PROGRAM STRUCTURE	3-1
3.2.1	Blocks	3-1
3.2.2	Words	3-2
3.2.3	Program Number	3-4
3.2.4	Sequence Number	3-5
3.2.5	Optional Block Delete	3-5
3.2.6	Definition Blocks	3-5
3.3	PARAMETRIC PART PROGRAMMING LANGUAGE (3PL)	3-6
3.3.1	Labels	3-6
3.3.2	Arithmetic Expressions	3-6
3.3.3	Variable Substitution	3-8
3.3.4	Conditional Part Program Execution	3-9
3.4	MACRO SUBROUTINES	3-10
3.4.1	Macro Definition	3-10
3.4.2	Macro Call Command	3-11
3.5	EXAMPLE FOR THE USE OF THE EXPRESSION EVALUATOR	3-12
3.6	REPETITIVE PROGRAMMING	3-14
CHAPTER 4		COORDINATE WORDS
4.1	OVERVIEW	4-1
4.2	CONTROLLED AXIS	4-2
4.3	COORDINATE SYSTEMS	4-2
4.3.1	Machine Coordinate System	4-2
4.3.2	Part Program Coordinate System	4-4
4.3.3	Software Limits	4-6
4.4	TOOL LENGTH OFFSET	4-6
4.5	ABSOLUTE AND INCREMENTAL PROGRAMMING	4-10
4.6	POLAR COORDINATES	4-11
4.7	TRANSFORMATIONS	4-13
4.7.1	Rotation	4-13
4.7.2	Scaling	4-16

4.7.3	Translation	4-17
4.7.4	Mirror Image (G30,G31,G32)	4-18

CHAPTER 5 PREPARATORY FUNCTIONS (G FUNCTIONS)

5.1	OVERVIEW	5-1
5.2	PLANE SELECTION	5-3
5.3	POSITIONING (G0)	5-4
5.4	LINEAR INTERPOLATION (G1)	5-4
5.5	CIRCULAR INTERPOLATION (G2,G3)	5-5
5.5.1	Circular Programming	5-6
5.5.2	Circular Interpolation By Radius Programming	5-7
5.6	HELICAL INTERPOLATION (G12,G13)	5-8
5.7	FILLET PROGRAMMING (G22,G23)	5-10
5.8	DWELL (G4)	5-11
5.9	PROGRAMMING OF ABSOLUTE ZERO POINT (G92)	5-11
5.10	INCH/METRIC CONVERSION (G70,G71)	5-13

CHAPTER 6 CANNED CYCLES

6.1	OVERVIEW	6-1
6.2	Z AXIS CYCLES	6-1
6.2.1	Drill/Bore/Tap Cycles	6-1
6.2.2	Deep Hole Drilling Cycles	6-7
6.3	MULTI-HOLE Z AXIS CYCLES	6-9
6.3.1	Row Drilling Bolt Circles - Incremental Hole To Hole Distance	6-9
6.3.2	Row Drilling And Bolt Circles - Number Of Holes	6-11
6.3.3	Frame Drilling - Number Of Holes	6-13
6.4	MILL CYCLES	6-14
6.4.1	Outside/Inside Frame Mill	6-16
6.4.2	Pocket Frame Mill	6-18
6.4.3	Outside/Inside Face Mill	6-19
6.4.4	Outside/Inside Circle Mill	6-21
6.4.5	Slot Mill	6-23

CHAPTER 7 CUTTER DIAMETER COMPENSATION

7.1	OVERVIEW	7-1
7.2	CUTTER DIAMETER DATA ENTRY	7-2
7.3	PLANE SELECTION	7-3
7.4	CUTTER DIAMETER COMPENSATION COMMANDS	7-3
7.5	ENTRY INTO CUTTER DIAMETER COMPENSATION	7-4
7.6	BLOCK INTERACTIONS	7-5
7.7	EXIT FROM CUTTER DIAMETER COMPENSATION	7-12
7.8	FACTORS AFFECTING USE OF CUTTER COMPENSATION	7-13

CHAPTER 8 FEED FUNCTION (F FUNCTIONS)

8.1	OVERVIEW	8-1
8.2	RAPID TRAVERSE FEEDRATE	8-1
8.3	CUTTING FEEDRATE	8-2
8.4	FEEDRATE OVERRIDE	8-2
8.5	CONSTANT SURFACE FEED	8-3

CHAPTER 9 AUXILIARY MACHINE CONTROL FUNCTIONS

9.1	SPINDLE SPEED (S FUNCTION)	9-1
9.2	TOOL FUNCTION (T FUNCTION)	9-1
9.3	MISCELLANEOUS FUNCTION COMMANDS	9-3
9.3.1	PROGRAM STOP (M0)	9-3
9.3.2	OPTIONAL STOP (M1)	9-4
9.3.3	PROGRAM REWIND (M2)	9-4
9.3.4	TOOL CHANGE (M6)	9-4
9.3.5	COOLANT (M7,M8,M9)	9-5
9.3.6	MOVE TO CLEAR POINT (M20,M21,M22,M26)	9-5
9.3.7	QUILL HOME (M25)	9-6
9.3.8	INDEX TABLE (M51)	9-6
9.4	OPERATOR MESSAGES	9-6

APPENDIX A INDEX

LIST OF ILLUSTRATIONS

FIGURE		PAGE
4-1	Machine Coordinate System	4-3
4-2	Part Program Coordinate System	4-5
4-3	Tool Length Differences	4-7
4-4	Measuring Actual Preset	4-8
4-5	Translating The Z Coordinates	4-9
4-6	Incremental And Absolute Programming	4-10
4-7	Cam Track	4-12
4-8	Rotor, Geneva Mechanism	4-15
5-1	CW or CCW in Switchable Plane	5-3
6-1	Feed and Speed Chart for Tapping	6-4
7-1	Programming Commands for Cutter Compensation	7-4
9-1	Series I CNC Spindle Drive HP vs. Speed Characteristics	9-2