

MANUAL NO. M-111B
PROGRAMMING MANUAL FOR
SERIES II 2 & 3 AXIS CONTINUOUS PATH SYSTEMS
WITH BRIDGEPORT CONTROLS

S/N 651 & Up

SPECIFICATIONS

XNC2BC2CP
XNC2BC3CP


FOREWORD

This manual contains programming examples and instructions for the effective control of a machine tool with coded punched tape. The Bridgeport Series II machine with Bridgeport Controls is described in detail in the Operation and Maintenance Manual M 110 and is illustrated in the frontispiece of this volume. All required procedures for programming this Incremental System are contained herein.

July 1974

Bridgeport machines[®]

• **teatron** company 500 LINDLEY STREET, BRIDGEPORT, CONN. 06606



BRIDGEPORT SERIES II N/C MILLING MACHINE

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
I	PART PROGRAMMING 1-1
1.1	Introduction 1-1
1.2	The Part Programmer 1-2
1.3	Programming for N/C 1-3
1.4	The N/C Coordinate System 1-6
II	MACHINE AND CONTROL SPECIFICATIONS 2-1
2.1	Axis Travel Ranges 2-1
2.2	Accuracy 2-1
2.3	Spindle 2-2
2.4	Feed Range 2-5
2.5	Weight 2-5
2.6	Axial Force at Spindle 2-5
III	TAPE CODES AND FORMATS 3-1
3.1	Control Tape 3-1
3.2	Tab Sequential Format 3-2
3.3	Programming Sheets 3-5
3.4	Block of Data Description 3-5
IV	MANUAL PROGRAMMING 4-1
4.1	Point-to-Point Programming 4-1
Example No. 1.	Point-to-Point Drilling (2 Axis) 4-7
Example No. 2.	Point-to-Point Drilling (3-Axis) 4-8
Example No. 3.	End Cap, PARTNO 050115 4-10
Example No. 4.	End Cap, PARTNO 050115 (Z Axis) 4-14
4.2	Continuous Path Programming 4-17
Example No. 5.	Contour Milling a Slot 4-24
Example No. 6.	Valve Seat, PARTNO 050118 4-28
Example No. 7.	Plate, PARTNO 050117 4-31
V	COMPUTER ASSISTED PART PROGRAMMING 5-1
5.1	Fundamentals of APT 5-4
5.2	Organization of APT 5-11
5.3	Postprocessor Vocabulary 5-15
5.4	Notes on Part Programming 5-37
5.5	Diagnostics 5-38
5.6	Part Program Development 5-40
APPENDIX A: NOMINAL MACHINING FEEDS AND SPEEDS A-1	
APPENDIX B: GLOSSARY OF PROGRAMMING TERMS B-1	

LIST OF ILLUSTRATIONS

<u>Figure</u>		<u>Page</u>
1-1	Example of Positioning and Contouring	1-4
1-2	The N/C Coordinate System	1-7
1-3	The Bridgeport Coordinate System	1-8
2-1	Axis Travel Ranges	2-3
2-2	Accuracy Cutting Test	2-4
2-3	Horsepower vs Spindle Speed	2-6
2-4	Axial Force at Spindle	2-6
3-1	Punched Paper Tape	3-3
3-2	Bridgeport N/C Codes	3-3
3-3	Typical Block of Information	3-3
3-4	Bridgeport N/C Part Program Sheet	3-6
3-5	Arc Programming Examples	3-9
3-6	Summary of Sign Values for CW and CCW Arcs	3-10
3-7	Misprogrammed Circles	3-11
3-8	Typical Acceleration/Deceleration Curves	3-13
3-9	Minimum Axis Moves vs Feedrates	3-15
3-10	Quill Drive Unit	3-19
3-11	Quill Cycles	3-21
4-1	Typical Classification List	4-2
4-2	Tool Length Compensation	4-3
4-3	Simplified Point-to-Point Drilling Example	4-7
4-4	Point-to-Point Drilling (3 Axis)	4-8
4-5	End Cap, PARTNO 050115	4-10
4-6	Allowance for Cutter Offset	4-19
4-7	Climb Milling vs Conventional Milling	4-20
4-8	Contour Milling a Slot	4-24
4-9	Trigonometry Example	4-25
4-10	Trigonometry Example	4-26
4-11	General Solution of Line-Line Intersection	4-27
4-12	Valve Seat, PARTNO 050118	4-28
4-13	Plate, PARTNO 050117	4-31
4-14	Plate, Cutter Path and Program Dimensions	4-32
5-1	Typical N/C Operation Sequence Flow Chart	5-8
5-2	APT System Flow Diagram	5-11