


FRONTISPIECE.



by Charles Scribner's Sons.

Modern

MACHINE-SHOP PRACTICE

 $\mathbf{B}\mathbf{Y}$



JOSHUA ROSE, M.E.



ILLUSTRATED WITH MORE THAN 3000 ENGRAVINGS

VOLUME I.

NEW YORK
CHARLES SCRIBNER'S SONS
1887

10/14

COPYRIGHT, 1887, BY CHARLES SCRIBNER'S SONS

PREFACE.

ODERN MACHINE-SHOP PRACTICE is presented to American mechanics as a complete guide to the operations of the best equipped and best managed workshops, and to the care and management of engines and boilers.

The materials have been gathered in part from the author's experience of thirty-one years as a practical mechanic; and in part from the many skilled workmen and eminent mechanics and engineers who have generously aided in its preparation. Grateful acknowledgment is here made to all who have contributed information about improved machines and details of new methods.

The object of the work is practical instruction, and it has been written throughout from the point of view, not of theory, but of approved practice. The language is that of the workshop. The mathematical problems and tables are in simple arithmetical terms, and involve no algebra or higher mathematics. The method of treatment is strictly progressive, following the successive steps necessary to becoming an intelligent and skilled mechanic.

The work is designed to form a complete manual of reference for all who handle tools or operate machinery of any kind, and treats exhaustively of the following general topics: I. The construction and use of machinery for making machines and tools; II. The construction and use of work-holding appliances and tools used in machines for working metal or wood; III. The construction and use of hand tools for working metal or wood; IV. The construction and management of steam engines and boilers. The reader is referred to the Table of Contents for a view of the multitude of special topics considered.

The work will also be found to give numerous details of practice never before in print, and known hitherto only to their originators, and aims to be useful as well to master-workmen as to apprentices, and to owners and managers of manufacturing establishments equally with their employees, whether machinists, draughtsmen, wood-workers, engineers, or operators of special machines.

The illustrations, over three thousand in number, are taken from modern practice; they represent the machines, tools, appliances and methods now used in the leading manufactories of the world, and the typical steam engines and boilers of American manufacture.

The new Pronouncing and Defining Dictionary at the end of the work, aims to include all the technical words and phrases of the machine shop, both those of recent origin and many old terms that have never before appeared in a vocabulary of this kind.

The wide range of subjects treated, their convenient arrangement and thorough illustration, with the exhaustive Table of Contents of each volume and the full Analytical Index to both, will, the author hopes, make the work serve as a fairly complete ready reference library and manual of self-instruction for all practical mechanics, and will lighten, while making more profitable, the labor of his fellow-workmen.

CONTENTS.

VOLUME I.

CHAPTER I.		PA	AG
		Influence of the size of the rolling circle upon the amount of	
THE TEETH OF GEAR-WHEELS.	PAGE	flank contact	I
Gear-Wheels. Spur-wheels, bevel-wheels, mitre-wheels, crown-			1
wheels, annular or internal wheels	ı	The smaller the diameter of the rolling circle, the less the	•
Trundle-wheels, rack and pinion-wheel and tangent screw.		sliding motion	1
or worm and worm-wheel	1	Influence of the size of the rolling upon the number of teeth	
The diameter of the pitch circle of	1	in contact in a given pair of wheels	1
Gear-Wheel Teeth. The face, the flank, the depth or height	I	Demonstration that the degrees of angle the teeth move	
The space, the pitch line, the point, the arc pitch, the chord		through exceed those of the path of contact, unless the	
pitch, the line of centres	2	tooth faces meet in a point	I
of natural sines; diametral pitch; finding the arc from		teeth in contact	2
the diametral pitch; table of arc and diametral pitches	3	Increasing the arc of recess without increasing the arc of ap-	٠
Gear-Wheels. The driver and follower, a train of gears	3	proach	20
Intermediate gears	3	Wheels for transmitting motion rather than power	2
The velocity of compounded wheels	4	Clock wheels	2
Finding the diameters of the pitch circles of	4	Forms of teeth having generating or rolling circles, as large	
Considered as revolving levers	5	or nearly as large as the diameters of the wheelsGear-Wheels. Bevel	2
The angular velocity of	5	The principles governing the formation of the teeth of bevel-	2.
Gear-Wheels. Hunting tooth in, stop motion of	7	wheels	2
Gear-Wheel Teeth. The requirements and nature of the teeth	1	Demonstration that the faces of the wheels must be in line	
curves	- 7	with the point of intersection of the axis of the two shafts	22
Cycloidal curves for the faces of; epicycloidal and involute		Gear Teeth. Method of finding the curves of, for bevel gear	22
curves; the hypocycloidal curve; method of forming or		Gear-Wheels. Internal or annular	2
generating the epicycloidal and hypocycloidal curves for the faces and flanks of gear teeth	8	Demonstration that the teeth of annular wheels correspond to the spaces of spur-wheels	_
Applications of the epicycloidal and hypocycloidal curves in	. 0	Gear-Wheels Internal. Increase in the length of the path of	2
the formation of gear teeth	9	contact on spur-wheels of the same diameter, and having	
The diameter of the circle for generating the epicycloidal	1	the same diameter of generating or rolling circle	2
and hypocycloidal curves; graphical demonstration that		Demonstration that the teeth of internal wheels may inter-	
the flank curves are correctly formed to work with the		fere when spur-wheels would not do so	2
face curves of the other wheel	io	Methods of avoiding the above interference	23
pendent of either the respective sizes of the wheels, or of		The teeth of : demonstration that it is practicable to so form	2
the curve generating circles	11	the teeth faces that they will have contact together as well	
Gear-Wheels. Hand applications of the rolling or generating		as with the flanks of the other wheel	2
circle to mark the tooth curves for a pair of wheels	12	Intermediate rolling circle for accomplishing the above re-	
Gear-Wheel Teeth. The variation of curve due to different di-		Sult	24
ameters of wheels or of rolling circles	12	The application of two rolling circles for accomplishing the above result	
gear-wheels; definition of the "arc of approach;" defini-		Demonstration that the result reached by the employment of	24
tion of the "arc of recess;" demonstration that the flanks		two rolling circles of proper diameter is theoretically and	
of the teeth on the driver or driving-wheel have contact		practically perfect	24
with the faces of the driven wheel during the arc of ap-		Limits of the diameters of the two rolling circles	25
proach, and with the flanks of the driven wheel during the	70	Increase in the arc of contact obtained by using two rolling circles.	۵.
arc of recess	13	Demonstration that the above increase is on the arc of recess	25
of centres, when motion rather than power is to be con-			25
veyed	13	Demonstration that by using two rolling circles each tooth	•
Demonstration that the appearance or symmetry of a tooth		has for a certain period two points of contact	25
has no significance with regard to its action	14	The laws governing the diameters of the two rolling circles.	25
Finding how many teeth will be in constant action, the di- ameter of the wheels, the pitch of the teeth, and the diam-	- [Practical application of two rolling circles Demonstration that by using two rolling circles the pinion	20
eter of the rolling circle being given	15	may contain but one tooth less than the wheel	26
Example of the variation of tooth form due to variation of		The sliding and rolling motion of the teeth of	2
wheel diameter	15		•
Gear Teeth. Variation of shape from using different diameters		CHAPTER II.	
of rolling circles	16		
Thrust on the wheel shafts caused by different shapes of teeth	16	THE TEETH OF GEAR-WHEELS (Continued).	
Gear-Wheels. Willis' system of one size of rolling circle for		Worm and Worm-Wheel, or wheel and tangent screw28 to	91
trains of interchangeable gearing	16	General description of	28
Conditions necessary to obtain a uniform velocity of	16	Qualifications of	28
Gear Teeth. The amount of rolling and of sliding motion of	16	The wear of	28
The path of the point of contact of	16		28
The arcs of approaching and of receding contact Lengths of the arcs of approach and of recess	16	When straight have contact on the centres only of the tooth sides	~ (
The influence of the sizes of the wheels upon the arcs of con-			28
tact	17	The location of the pitch line of the worm	28

		AGE	P .	AGE
	The proper number of teeth in the worm-wheel	29	Angular or helical teeth	69
	Locating the pitch line of the worm so as to insure dura-		End thrust of angular teeth	69
	bility	29	Herring-bone angular teeth	69
	Rule for finding the best location for the pitch line of the		For transmitting motion at a right angle by means of angular	. ,
	worm	29	or helical teeth	69
	Increasing the face of the worm to obtain a smoother action	20	or helical teeth	69
Wor	as, to work with a square thread	29	For wheels whose shaft axes are neither parallel nor meeting	70
Worr	1-Wheels, applications of	30	Elliptical	
	Wheels with involute teeth		Elliptical, marking the pitch lines of	70
	Teeth. Generating the involute curve	1	Elliptical drawing the teeth ourses of	70
Gcar		31	Elliptical, drawing the teeth curves of	73
Tarrol.	Templates for marking the involute curve	32	For variable motion	
Coon	Tack Post of White of a selection for a select	34	Form of worm to give a period of rest	
Gear	Teeth, Pratt and Whitney's machine for cutting templates		Various applications of	74
	for	35	Gear-Wheels, arrangement of, for periodically reversing the di-	
			rection of motion	75
	CHAPTER III.		Watt's sun and planet motion	75
		I	Arrangements for the rapid multiplication of motion	75
	THE TEETH OF GEAR-WHEELS (Continued).		Arrangement of, for the steering gear of steam fire-	
	Till I Di I di Till I (Commada),		engines	75
Gear	Teeth, revolving cutters for	37	Various forms of mangle gearing	79
	Pantagraph engine for dressing the cutters for	38	Gear-Wheel and Rack, for reciprocating motion	77
	Numbers of cutters used for a train of wheels	39	Friction Wheels	77
Gear-	Wheel Teeth. Table of equidistant value of cutters	41	The material for	77
GCa1-	Depth of, in the Brown and Sharpe system	42	Paper	78
	Cutting the teeth of worm-wheels	42	For the feed motion of machines	
			The unequal wear upon grooved	7 9
	Finding the angle of the cutter for cutting worm-wheels The construction of templates for rolling the tooth curves	43	Form of, for relieving the journals of strain	79
		43	Cams, for irregular motion	80
	Rolling the curves for gear teeth	43	Finding the pitch line of	80
	Forms of templates for gear teeth	44	Finding the working face of	80
	Pivoted arms for tooth templates	44	The effect the diameter roller has upon the motion produced	, ,
	Marking the curves by hand	45	by a cam	80
	Former or Template of the Corliss bevel gear-wheel engine		Demonstration of the different motion produced by different	
	or cutting machine	45	diameters of rollers upon the same cam	80
	The use of extra circles in marking the curves with com-		Diagram of motion produced from the same cam with differ-	00
	passes	46		c -
	Finding the face curves by geometrical constructions	47	ent diameters of rollers	01
	The Willis odontograph for finding the radius for striking		Return or backing	82
	the curves by hand	47	Methods of finding the shape of return or backing	82
	The method of using the Willis odontograph	48	Cam Motion, for an engine slide valve without steam lap	83
	Professor Robinson's odontograph	49	For a slide valve with steam lap	83
	Method of using Professor Robinson's odontograph	49	Groove Cams, proper construction of	
	Application of Professor Robinson's odontograph for trains		The wear of	84
	of gearing	51	Brady's improved groove cam with rolling motion and ad-	
	Tabular values and setting numbers for Professor Robinson's		justment for wear	84
	odontograph	~ -		
		51		
	Walker's patent wheel scale for marking the curves of cast	51	CHAPTER IV.	
	Walker's patent wheel scale for marking the curves of cast teeth	51 51	CHAPTER IV.	
	Walker's patent wheel scale for marking the curves of cast teeth	51 53	CHAPTER IV. SCREW-THREADS.	
	Walker's patent wheel scale for marking the curves of cast teeth	51 53 53	SCREW-THREADS.	
	Walker's patent wheel scale for marking the curves of cast teeth	51 53	SCREW-THREADS. Screw Threads, the various forms of	
	Walker's patent wheel scale for marking the curves of cast teeth	51 53 53 54	SCREW-THREADS. Screw Threads, the various forms of	85
	Walker's patent wheel scale for marking the curves of cast teeth	51 53 53	SCREW-THREADS. Screw Threads, the various forms of	85 85
	Walker's patent wheel scale for marking the curves of cast teeth	51 53 53 54 54	SCREW-THREADS. Screw Threads, the various forms of The pitch of Self-locking. The Whitworth	85 85 86
	Walker's patent wheel scale for marking the curves of cast teeth	51 53 53 54 54 54 55	SCREW-THREADS. Screw Threads, the various forms of	85 86 86
	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth	51 53 53 54 54 54 55 56	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V.	85 86 86 86
	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth	51 53 53 54 54 54 55	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of.	85 86 86 86 86
	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an	51 53 53 54 54 55 56 56	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting.	85 86 86 86 86 86
	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth.	51 53 53 54 54 54 55 56	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening.	85 86 86 86 86 86
	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an	51 53 53 54 54 55 56 56	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools	85 86 86 86 86 86 86 86 86
	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth.	51 53 53 54 54 55 56 56	SCREW-THREADS. Screw Threads, the various forms of The pitch of Self-locking. The Whitworth The United States standard. The Common V The requirements of Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools Methods of producing.	85 86 86 86 86 86
Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for.	51 53 53 54 54 54 55 56 56	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools Methods of producing. Alteration of shape of, from the wear of the tools they are	85 86 86 86 86 87 88 88
G ear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel.	51 53 53 54 54 55 56 56 58	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools Methods of producing. Alteration of shape of, from the wear of the tools they are cut by.	85 86 86 86 86 86 86 86 88 88 88
Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the	51 53 53 54 54 55 56 56 58 58 59	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by Screw Thread Cutting Tools. The wear of the tap and the die	85 86 86 86 86 86 86 86 86 86 86 86 86 86
Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel.	51 53 53 54 54 55 56 56 58 59 59	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear.	85 86 86 86 86 86 86 86 88 88 88
	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel.	51 53 53 54 54 55 56 56 58 59 59	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the	85 85 86 86 86 87 88 88 89 90
	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth.	51 53 53 54 54 55 56 56 58 59 59 59 60 60	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit.	855 865 866 867 878 888 889 909
Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe	51 53 53 54 54 54 55 56 56 58 59 59 60 60 60	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for.	85 86 86 86 86 87 88 88 89 90
Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe Wheels, Skew Bevel. Finding the line of contact.	51 53 53 54 54 55 56 56 58 58 59 60 60 60 60 61	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard	85 86 86 86 87 88 88 88 89 90 90
Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth.	51 53 53 54 54 55 55 56 56 58 59 59 60 60 60 60 61	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread.	855 866 866 867 87 888 888 899 90
Gear- Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up.	51 53 53 54 54 55 56 56 58 58 59 59 60 60 60 60 61 61	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for.	855 866 866 867 87 888 888 899 90
Gear- Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw.	51 53 53 54 54 55 56 56 58 59 59 60 60 60 61 61 62	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for.	855 868 868 868 878 888 899 9091
Gear- Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast.	51 53 53 54 54 54 55 56 56 58 59 59 60 60 60 61 61 62 62	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts.	855 868 868 868 878 888 889 90 91 91 91 92
Gear- Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe.	51 53 53 54 54 54 55 56 56 58 59 59 60 60 60 61 61 62 62 62	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread.	855 866 866 867 878 888 889 900 911 911 921 922 923
Gear- Gear- Gear- Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand.	51 53 53 54 54 55 56 56 58 58 59 59 60 60 60 60 61 61 62 62 62 62	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes	855 866 866 867 878 888 899 90 91 91 92 93 93
Gear- Gear- Gear- Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe Cutting the teeth by hand. Wheels, Mortise or cogged.	51 53 53 54 54 55 56 56 58 59 59 60 60 60 61 62 62 62 62 63	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads.	855 866 866 867 878 888 889 900 911 911 921 922 923
Gear- Gear- Gear- Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division innes on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs.	51 53 53 54 54 55 56 56 58 59 59 60 60 60 61 61 62 62 62 63 63	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the	855 866 866 867 878 888 899 90 91 91 92 93 93 95
Gear- Gear- Gear- Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of fastening cogs.	51 53 53 54 54 55 56 56 58 59 59 60 60 60 61 61 62 62 62 63 63 63	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread.	855 866 866 868 868 868 868 868 969 979 979 979 979 979 979 979 979 979
Gear- Gear- Gear- Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of fastening cogs. Methods of fastening cogs. Methods of feethin, calculating the strength of epicycloidal.	51 53 53 54 54 55 56 56 58 58 59 59 60 60 60 61 61 62 62 63 63 63 63 64	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread. Table of Whitworth's screw threads for gas, water, and hy-	855 866 866 867 875 888 888 888 90 91 91 92 92 93 93 95
Gear- Gear- Gear- Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bovel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of getting out cogs for. Wheel Teeth, calculating the strength of epicycloidal. Factors of safety for.	51 53 53 54 54 55 56 56 58 59 59 60 60 60 61 62 62 62 63 63 63 64 64	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread. Table of Whitworth's screw threads for gas, water, and hydraulic piping.	855 866 866 867 868 868 868 868 969 919 919 919 919 919 919 919 919 919
Gear- Gear- Gear- Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of getting out cogs for. Wheel Teeth, calculating the strength of epicycloidal. Factors of safety for. Tredgold's rule for calculating the strength of.	51 53 53 54 54 55 56 56 58 59 59 60 60 61 61 62 62 62 63 63 63 64 64 65	Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread. Table of Whitworth's screw threads for gas, water, and hydraulic piping. Whitworth's standard gauges for watch and instrument	85 86 86 86 86 86 86 86 86 86 86 86 86 86
Gear-Gear-Gear-Gear-Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division on the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of getting out cogs for. Wheel Teeth, calculating the strength of epicycloidal. Factors of safety for. Tredgold's rule for calculating the strength of. Cut, calculating the strength of.	51 53 53 54 54 55 56 56 58 59 59 60 60 60 61 61 62 62 62 63 63 64 64 65 66 66 66 66 66 66 66 66 66 66 66 66	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread. Table of Whitworth's screw threads for gas, water, and hydraulic piping.	855 866 866 867 868 868 868 868 868 969 979 979 979 979 979 979 979 979 979
Gear-Gear-Gear-Gear-Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of fastening cogs. Methods of getting out cogs for. Wheel Teeth, calculating the strength of epicycloidal. Factors of safety for. Tredgold's rule for calculating the strength of. Cut, calculating the strength of. Wheel Teeth. The strength of cogs.	51 53 53 54 54 55 56 56 58 58 59 59 60 60 60 61 61 62 62 63 63 63 64 64 65 65 66 66 66 66 66 66 66 66 66 66 66	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread. Table of Whitworth's screw threads for gas, water, and hydraulic piping. Whitworth's standard gauges for watch and instrument makers. Screw-cutting hand tools	855 866 866 867 868 868 868 868 969 919 919 919 919 919 919 919 919 919
Gear-Gear-Gear-Gear-Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of fastening cogs. Methods of setting out cogs for. Wheel Teeth, calculating the strength of epicycloidal. Factors of safety for. Tredgold's rule for calculating the strength of. Cut, calculating the strength of cogs. The thickness of cogs.	51 53 53 54 54 55 56 56 58 58 59 59 60 60 60 61 61 62 62 62 63 63 63 64 66 66 66 66 66 66 66 66 66 66 66 66	SCREW-THREADS. Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread. Table of Whitworth's screw threads for gas, water, and hydraulic piping. Whitworth's standard gauges for watch and instrument makers. Screw-cutting hand tools. Thread-Cutting Tools. American and English forms of stocks	8 5 8 6 8 6 8 6 8 6 8 6 8 6 8 6 8 6 8 6
Gear-Gear-Gear-Gear-Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of fastening cogs. Methods of getting out cogs for. Wheel Teeth, calculating the strength of epicycloidal. Factors of safety for. Tredgold's rule for calculating the strength of. Cut, calculating the strength of cogs. The thickness of cogs. The thickness of cogs. The thickness of cogs.	51 53 53 54 54 55 56 56 58 58 59 59 60 60 60 61 61 62 62 62 63 63 63 64 64 65 66 66 66 66 66 66 66 66 66 66 66 66	Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread. Table of Whitworth's screw threads for gas, water, and hydraulic piping. Whitworth's standard gauges for watch and instrument makers. Screw-cutting Tools. American and English forms of stocks and dies.	8 5 8 6 8 6 8 6 8 6 8 6 8 6 8 6 8 6 8 6
Gear-Gear-Gear-Gear-Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division innes on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of fastening cogs. Methods of setting out cogs for. Wheel Teeth, calculating the strength of epicycloidal. Factors of safety for. Tredgold's rule for calculating the strength of. Cut, calculating the strength of cogs. The thickness of cogs. The thickness of cogs. Table for calculating the strength of different kinds of.	51 53 53 54 54 55 56 56 58 58 59 59 60 60 60 61 61 62 62 62 62 63 63 64 64 65 66 66 66 66 66 66 66 66 66 66 66 66	Screw Threads, the various forms of The pitch of Self-locking The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread. Table of Whitworth's screw threads for gas, water, and hydraulic piping. Whitworth's standard gauges for watch and instrument makers. Screw-cutting hand tools. Thread-Cutting Tools. American and English forms of stocks and dies. Adjustable or jamb dies	85858688688688888888888888888888888888
Gear-Gear-Gear-Gear-Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of fastening cogs. Methods of safety for. Tredgold's rule for calculating the strength of. Cut, calculating the strength of. Wheel Teeth. The strength of cogs. The durability of cogs. The durability of cogs. The durability of cogs. Table for calculating the strength of different kinds of. The contact of cast teeth.	51 53 53 54 54 55 56 56 58 58 59 59 60 60 60 61 61 62 62 62 63 63 63 64 64 65 66 66 66 66 66 66 66 66 66 66 66 66	Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread. Table of Whitworth's screw threads for gas, water, and hydraulic piping. Whitworth's standard gauges for watch and instrument makers. Screw-cutting hand tools. Thread-Cutting Tools. American and English forms of stocks and dies. Adjustable or jamb dies The friction of jamb dies	8 5 8 6 8 6 8 8 8 8 8 8 8 9 9 9 9 9 9 9 9 9
Gear-Gear-Gear-Gear-Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of fastening cogs. Methods of setting out cogs for. Wheel Teeth, calculating the strength of epicycloidal. Factors of safety for. Tredgold's rule for calculating the strength of. Cut, calculating the strength of cogs. The durability of cogs. The durability of cogs. Table for calculating the strength of different kinds of. The contact of cast teeth. Table for determining the relation between pitch diameter,	51 53 53 54 54 55 56 56 58 58 59 59 60 60 60 61 61 62 62 62 63 63 63 64 66 66 66 66 66 66 66 66 66 66 66 66	Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread. Table of Whitworth's screw threads for gas, water, and hydraulic piping. Whitworth's standard gauges for watch and instrument makers. Screw-cutting hand tools. Thread-Cutting Tools. American and English forms of stocks and dies. Adjustable or jamb dies. The friction of jamb dies. The sizes of hobs that should be used on jamb dies.	8 5 8 6 8 6 8 8 8 8 8 8 8 9 9 9 9 9 9 9 9 9
Gear-Gear-Gear-Gear-Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of fastening cogs. Methods of getting out cogs for. Wheel Teeth, calculating the strength of epicycloidal. Factors of safety for. Tredgold's rule for calculating the strength of. Cut, calculating the strength of cogs. The thickness of cogs. The thickness of cogs. The durability of cogs Table for calculating the strength of different kinds of. The contact of cast teeth. Table for determining the relation between pitch diameter, pitch, and number of teeth in gear-wheels.	51 53 53 54 54 55 56 56 58 59 59 60 60 61 61 62 62 62 63 63 63 64 66 66 66 66 66 66 66 66 66 66 66 66	Screw Threads, the various forms of The pitch of Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread. Table of Whitworth's screw threads for gas, water, and hydraulic piping. Whitworth's standard gauges for watch and instrument makers. Screw-cutting hand tools. Thread-Cutting Tools. American and English forms of stocks and dies. Adjustable or jamb dies. The sizes of hobs that should be used on jamb dies. Cutting right or left-hand thread with either single, double,	8 5 8 6 8 6 8 8 8 8 8 8 8 9 9 9 9 9 9 9 9 9
Gear-Gear-Gear-Gear-Gear-	Walker's patent wheel scale for marking the curves of cast teeth. The amount of side clearance in cast teeth. Filleting the roots of epicycloidal teeth with radial flanks. Scale of tooth proportions given by Professor Willis. The construction of a pattern for a spur-wheel that is to be cast with the teeth on. Template for planing the tooth to shape. Method of marking the curves on teeth that are to be glued on Method of getting out the teeth of. Spacing the teeth on the wheel rim. Methods of accurately spacing the pattern when it has an even number of teeth. Method of spacing the wheel rim when it has an odd number of teeth. Wheels, Bevel Pinion, drawings for. Getting out the body for a bevel-wheel. Template for marking the division lines on the face of the wheel. Marking the lines of the division on the wheel. Wheels, Pinion, with dovetail teeth. Testing the angle of bevel-wheels while in the lathe. Wheels, Skew Bevel. Finding the line of contact. Marking the inclination of the teeth. Wheels, Bevel, drawing for built up. Wheels, Worm, or endless screw. Constructing a pattern from which the worm is to be cast. Tools for cutting the worm in a lathe. Cutting the teeth by hand. Wheels, Mortise or cogged. Methods of fastening cogs. Methods of fastening cogs. Methods of setting out cogs for. Wheel Teeth, calculating the strength of epicycloidal. Factors of safety for. Tredgold's rule for calculating the strength of. Cut, calculating the strength of cogs. The durability of cogs. The durability of cogs. Table for calculating the strength of different kinds of. The contact of cast teeth. Table for determining the relation between pitch diameter,	51 53 53 54 54 55 56 56 58 58 59 59 60 60 60 61 61 62 62 62 63 63 63 64 66 66 66 66 66 66 66 66 66 66 66 66	Screw Threads, the various forms of. The pitch of. Self-locking. The Whitworth The United States standard. The Common V. The requirements of. Tools for cutting. Variation of pitch from hardening. The wear of thread-cutting tools. Methods of producing. Alteration of shape of, from the wear of the tools they are cut by. Screw Thread Cutting Tools. The wear of the tap and the die Improved form of chaser to equalize the wear. Form of, to eliminate the effects of the wear in altering the fit. Originating standard angles for. Standard mirometer gauge for the United States standard screw thread. Standard plug and collar gauges for. Producing gauges for. Table of United States standard for bolts and nuts. Table of standard for the V-thread. United States standard for gas and steam pipes Taper for standard pipe threads. Tables of the pitches and diameters at root of thread, of the Whitworth thread. Table of Whitworth's screw threads for gas, water, and hydraulic piping. Whitworth's standard gauges for watch and instrument makers. Screw-cutting hand tools. Thread-Cutting Tools. American and English forms of stocks and dies. Adjustable or jamb dies. The friction of jamb dies. The sizes of hobs that should be used on jamb dies.	8 5 5 8 6 8 6 8 8 8 8 8 8 8 9 9 9 9 9 9 9 9 9

ix

	PAGE		PAGE
Various forms of stocks with dies adjustable to take up the		Foot	
wear	IOI	Methods of designating the sizes of	
Dies for gas and steam pipes.	IOI	Bench	130
Thread-Cutting Tool Taps. The general forms of taps	102	Power	
Reducing the friction of		Hand	
Giving clearance to	102	Slide Rest for	
The friction of taper	103	American form of, their advantages and disadvantages English forms of	132
Professor J. E. Sweet's form of tap	103	For spherical work	132
Adjustable standard		Methods of taking up lost motion of	122
The various shapes of flutes employed on taps		Engine Lathe, general construction of	122
The number of flutes a tap should have	105	The construction of the shears of	T34
Demonstration that a tap should have four cutting edges	3	Construction of the headstock	134
rather than three	106	Construction of the bearings	134
The position of the square or driving end, with relation to		Construction of the back gear	135
the cutting edges	106	Means of giving motion to the feed spindle	135
Taper taps for blacksmiths	106	Construction of the tailstock	
Collapsing taps for use in tapping machines	107	Method of rapidly securing and releasing the tailstock	
Collapsing tap for use in a screw machine	107	Lathe Tailstock, setting over for turning tapers	
The alteration of pitch that occurs in hardening		Engine Lathe, construction of carriage	137
Gauging the pitch after the hardening		Feed motion for carriage or saddle	137
Correcting the errors of pitch caused by the hardening	109	Lathe Apron. Construction of the feed traverse	138
For lead.	109	Construction of the cross-feed motion	
Elliptical in cross section		Engine Lathe, lead screw and change wheels of	
For very straight holes	109	Feed spindle and lead screw bearings Swing frame for lead screw	139
Tap wrenches solid and adjustable	110	Lead screw nuts	139
Thread-Cutting. Tapping Appliances for tapping standard work		With compound slide rest.	T40
-ippromoco for tapping standard work		Construction of compound slide rest	
CHAPTER V.		Advantages of compound slide rest	141
CHAFIER V.		For taper turning	142
FASTENING DEVICES.		Taper-turning attachments	142
		With compound duplex slide rest	143
Bolts, classification of, from the shapes of their heads		Detachable slide rest	143
Classification of, from the shapes of their bodies		Three-tool slide rest for turning shafting	143
Countersunk		With flat saddle for chucking work on	143
For foundations, various forms of		The Sellers Lathe	143
Hook bolts		Construction of the headstock and treble gear	144
The United States standard for finished bolts and nuts		Construction of the tailstock and method of keeping it in line.	
The United States standard for rough bolts and nuts, or		Construction of the carriage and slide rest	
black bolts	TT4	Car Axle Lathe, with central driving motion and two slide rests.	
The Whitworth standard for bolts and nuts	114	The feed motions of	T48
Screws		Self-Acting Lathe, English form of	148
Studs		Pattern Maker's Lathe	148
Set Screws		Brake for cone pulley	149
Bolts for quick removal		With wooden bed	149
That do not pass through the work		Slide rest for	149
That self-lock in grooves and are readily removable Heads and their bedding		Chucking Lathe, English	149
Nuts, the forms of, when they are to be steam tight.	11/	Feed motions of	150
Various forms of	TT8	Pulley Lathe	150
Jamb nuts and lock nuts.	IIO	Gap or Break Lathe	
Differential Threads for locking purposes		Extension Lathe	151
For fine adjustments	IIO	Chucking Lathe for boring purposes	151
Nuts, taking up the wear of	120	Lathe for turning crank axles.	154
Securing devices	120	Construction of the headstock	152
Securing by taper pins	121	Construction of the feed motions	154
Securing by cotters	121	For turning crank. Arrangements of the slide rests	154
Securing by notched plates		Application of the slide rest to a crank	
Pins. Securing for exact adjustments			
And double eyes fitting		CHAPTER VII.	
FixedWorking		DETAILS IN LATIT CONSTRUCTION	
Bolts, removing corroded	122	DETAILS IN LATHE CONSTRUCTION.	
Nuts, removing corroded.	122	Live Spindle of a lathe, the fit of	157
Washers, standard sizes of	122	With coned journals	157
Wrench, the proper angles of	123	Methods of taking up the end motion of	158
Box	124	Arranging the swing frame for the change gears	158
Monkey	125	Taking up the wear of the back bearing	158
Adjustable, various forms of		The Wear of the front bearing of	
Sockets		The Taper for the live centre	159
Novel for carriage bolts		Tapers for the live centres	159
Pin		Methods of removing the dead centre	159 TEO
Improved form of	120 126	Driving Cone, arranging the steps of	759 750
The bearing surfaces of		Requirements of proportioning the steps of	150
Set Screws, application of, to hubs or bosses		Rules for proportioning the diameters of the steps of, when	
Keys, with set-screws		the two pulleys are exactly alike and are connected by an	
The draught of	127	open belt	161
Feathers, and their applications	127	When the two pulleys are unlike	164
Keys, for parallel rods	128	Back Gear, methods of throwing in and out	165
Taper Pins, proper position of, for locking purposes		Conveying motion to the lead screw	105
Improved method of fitting	128	Attaching the swing frame	100
		Feed Gear. Arrangement for cutting worm threads or tangent screws	T6=
CHAPTER VI.		Feed Motion for reversing the direction of tool traverse in screw	107
TUE I ATUE		cutting	
THE LATHE.		For lathe aprons	168
Lathe, the importance and advantages of	129	Slide Rest, weighted elevated	168
Classification of lathes	129	Double tool holder for	169

		PAGE		PAGE
	Gibbed elevating	160	Threading tool for.	
Exan	uples of feed motions	170	Cutting-off tool for	208
Feed	Regulators for screw cutting	171	Special Lathe for wood working	208
	The star feed	172	The construction of the carriage and reducing knife	200
Ratch	et Feeds	173	Construction of the various feed motions	200
Tool	Holding devices, the various kinds of	173	Construction of the tailstock	200
Tool	Rest swiveling	174	Lathes for irregular forms	210
Tool	Holder for compound slide rests	174	Axe-handle	210
	For octagon boring tools	175	Back knife gauge	210
Lathe	Lead and Feed Screws	175	Special, for pulley turning	210
	Lead screws, supporting, long	176	Boring and Turning mill or lathe	211
	Position of the feed nut	177	Construction of the feed motions	211
	Form of threads of lead screws	177	Construction of the framing and means of grinding the lathe.	213
	The effect the form of thread has in causing the nut to lock	-//	Construction of the vertical feed motions	214
	properly or improperly		The Morton Poole roll turning lathe	215
	Example of a lead screw with a pitch of three threads per inch.	T77	Construction of the slide rest	215
	Example of a lead screw with five threads per inch	178	The tools for	210
	Example with a lead screw of five threads per inch		Special Lathes for brass work	210
	Device for correcting the errors of pitch of	179	Boring Lathe with traversing spindle	217
Table	for finding the change wheels for screw cutting when the	-19	For engine cylinders	210
- 45.0	teeth in the change wheels advance by four	180	Cylinder, with facing slide rests	219
	For finding the change wheels when the teeth in the wheels	100	With double heads and feeing roots	219
	advance by six	180	With double heads and facing rests. Lathe for turning Wheel hubs.	220
	Constructing a table to cut fractional threads on any lathe	180	Lattle for turning wheel hubs.	221
	Finding the change wheels necessary to enable the lathe to			
			CHADTED IV	
	cut threads of any given pitches	101	CHAPTER IX.	
Deta-	Finding the change wheels necessary to cut fractional pitches.	101		
Deter Lath-	mining the pitches of the teeth for change wheels	182	DRIVING WORK IN THE LATHE.	
Latne	Shears or beds	182		
	Advantages and disadvantages of, with raised V-guide-ways.	182	Drivers, carriers, dogs, or clamps, and their defects	222
T - 41	Examples of various forms of	183	Lathe clamps	
Latne	Shears with one V and one flat side	183	Equalizing drivers	222
	Methods of ribbing	184	The Clements driver	222
	The arrangement of the legs of	184	Driver and face plate for screw cutting	222
Lathe	Tailblock	185	Forms of, for bolt heads	224
	With rapid spindle motion	185	Adjustable, for bolt heads	224
	With rapid fastenings and releasing devices	185	For threaded work	224
	The wear of the spindles of	185	For steady rest work	225
	Spindles, the various methods of locking	186	For cored work.	225
	Testing, various methods of	187	For wood.	225
			Centres for hollow work	006
			For taper work	226
	CHAPTER VIII.		Lathe Mandrels, or arbors.	220
			Drivers for	
	SPECIAL FORMS OF THE LATHE.		For tubular work	22/
	or bonne forme of the entire.		Expanding mandrels	22/
TX7atc	hmaker's Lathes	-00	With expanding cones	227
vvaic	Construction of the headstock	100	With expanding cones	220
	Construction of chucks for		With expanding pieces	220
			Expanding, for large workFor threaded work	220
	Expanding chucks for	100	For nuts, various forms of	220
	Contracting chucks for		For nuts, various forms of	229
	Construction of the tailblock	189	For eccentric work	229
	Open spindle tailstocks for	189	Centring devices for crank axles	230
	Filing fixture for	189	The Steady Rest or back rest	231
	Fixture for wheel and pinion cutting	189	Steady rest, improved form of	
17040	Jewelers' rest for	189	Cone chuck	232
vv acc	h Manufacturers' Lathe	190	Steady rest for square and taper work	233
	Special chucks for	190	The cat head.	233
	Pump centre rest		Clamps for	233
	, hand		Follower rests.	234
	Screw slotting		Chucks and Chucking	234
	With variable speed for facing purposes	192	Simple forms of chucks	234
	Cutting-off machine		Adjustable chucks for true work	235
	Grinding Lathes		Two-jawed chucks	236
	With elevating rest		Box body chucks	237
	Universal		Reversible jawed chucks	237
	Special chucks for		Three and four-jawed chucks	237
	The Morton Poole calender roll grinding lathe	196	Combination chucks	237
	The construction of the bed and carriages	197	The wear of scroll chuck threads	237
	Principles of action of the carriages 197,	198	Universal chucks	238
	Construction of the emery-wheel arbors and the driv-		The wear of chucks	240
	ing motion		Special forms of chucks	241
	The advantages of		Expanding chucks for ring-work	241
	The method of driving the roll		Cement chuck	241
	Construction of the headstock		Chucks for wood-working lathes	242
	The transverse motion		Lathe Face Plates	243
	Brown and Sharpe Screw Machine, or screw-making lathe.		Face plates, errors in, and their effects	243
	Threading tools for		Work-holding straps	244
	Examples of the use of	203	Face plate, clamping work on	245
The S	ecor Screw Machine, construction of the headstock	204	Forms of clamps for	245
	The chuck	205	Examples of chucking work on 246,	247
	The feed gear		For wood work	247
	The turret		Special Lathe Chuck for cranks	248
	The cross slide	205	Face Plate Work, examples of	240
	The stop motions	206	Errors in chucking	
	and Whitney's Screw Machine		Movable dogs for	
	Parkhurst's wire feed, construction of the headstock, chuck		The angle plate	251
	and feed motion		Applications of	25 T
	Box tools for		Angle plate chucking, examples of	251
	Applications of box tools		Cross-head chucking	-251 251-
	E.A.			-55

CHAPTER X.	PAGE
CUTTING TOOLS FOR LATHES.	Boring Bars 289 Boring bar cutters 289
Principles governing the shapes of lathe tools	Three versus four cutters for boring bars
Diamond-pointed, or front tool	With sliding heads 290
Principles governing use of tools	Bar cutters, the shapes of
Front rake and clearance of front tools	Boring bars for taper work, various forms of 292
keenness	Boring double coned work 293 Boring bar, centres for 293
The effect of side rake	Cutting Speeds and feeds for wrought iron
The angle of clearance in lathe tools	Examples of speeds taken from practice 295
ters of work	CHAPTER XII.
Round-nosed tools	EXAMPLES IN LATHE WORK.
Judging the quantity of the tool from the shape of its cutting 259	Technical Terms used in the work
Square-nosed tools	Lathe Centres
Side tools for lathe work	Devices for truing
Cutting-off or grooving tools	Shapes of, for light and heavy work
Spring tools	Centre Drilling, attachment for lathes
Brass Work, front tools for 264 Side tools for 264	Machine
Threading tools 264	Combined centre-drill and countersink. 300 Countersink with adjustable drill. 300
Internal threading tools	Centring square 300
The level of threading tools	Centre-punch 300 Centre-punch guide 301
Gauges for threading tools	Centring work with the scribing block
Circular threading tools 267	Finding the centre of very rough work. 301 Centre-drill chuck. 302
Threading tool holders. 267 Chasers 268	The proper form of countersink for lathe work
Chaser holders	Various forms of square centres
Setting chasers	The advantage of the square centre for countersinking 303 Novel form of countersink for hardened work 303
Diameter at the roots of threads	Chucks for centre-drilling and countersinking 303
Cutting coarse pitch square threads	Recentring turned work
Tool Holders for outside work	Hand device for straightening lathe work 305
For circular cutters	Chuck for straightening wire
Combined tool holders and cutting-off tools	Roughing cuts, the change of shape of work that occurs from re-
	moving the surface by
CHAPTER XI.	Rates of feed for
DRILLING AND BORING IN THE LATHE.	Finishing cast-iron with water
The Twist Drill	Specks in finished cast-iron work
The diametral clearance of twist drills	Method of polishing lathe work
The front rake of twist drills	Filing lathe work
Demonstration of the common error in grinding twist drills. 276	The direction of tool feed in finishing long work 300.
The effects of improper grinding upon twist drills	Forms of laps for finishing gauges or other cylindrical lathe work
Grinding twist drills by hand	Forms of laps for finishing internal work 311
Twist drills for wood work	Grinding and polishing clamps for lathe work
Flat Drills for lathe work 280	Taper Work, turning 312
Holders for lathe work. 281 Half-round bit or pod auger. 281	The wear of the centres of
With front rake for wrought iron or steel 281	Gauge for setting over 313 Fitting 313
With adjustable cutter	Grinding 313
Chucking Reamer	The order of procedure in turning
Spacing the teeth of reamers	Special Forms. Curved work
Spiral teeth for reamers	Standard gauges for taper work
Various positions of emery-wheel in grinding reamers 282	Turning a cylinder cover 318
Chucking reamers for true work. 283 Shell reamers. 283	Turning pulleys
Arbor for shell reamers 283	Cutting Screws in the lathe
Rose-bit or rose reamers	The arrangement of the change gears
Adjustable reamers	The compounded gears 320
Stepped reamers for taper work. 285 Half-round reamers. 285	Finding the change wheels to cut a given thread 320 Finding the change wheels for a lathe whose gears are com-
Reamers for rifle barrels 285	pounded
Boring Tools for lathe work. 285 Countersinks. 285	Finding the change gears for cutting fractional pitches 321 To find what pitch of thread the wheels already on the lathe
Shapes of lathe boring tools	will cut
Boring tools for brass work	Cutting double threads 322
Boring tools for small work	Cutting screws whose pitches are given in the terms of the metric system
Boring Devices for Lathes 288	Cutting threads on taper work, 323
Boring Heads 288	Errors in cutting threads on taper work 324

CHAPTER XIII.	PAGI
EVAMPLES IN LATHE MODE (G	Fitting. Practicable methods of testing the fit of axle brasses
EXAMPLES IN LATHE WORK (Continued).	forced in by hydraulic pressure
Ball Turning with tubular saw	Shrinkage or contraction fits
With a single tooth on the end of a revolving tube 325	Gauge for
With a removable tool on an arbor	The shrinkage system at the Royal Gun Factory at
Tool holder with worm feed	Woolwich 36'
By hand 325	Experiments by Thomas Wrightson upon the shrink-
Cams, cutting in the lathe	age of iron under repeated heatings and coolings
Improved method of originating cams in the lathe 326	368 to 37. Shrinking work, to refit it
Motions for turning cams in the lathe	Shrinking work, to rent it
Cam chuck for irregular work	CHADTED XXX
Milling or knurling tool	CHAPTER XV.
Improved forms of	MEASURING TOOLS.
Winding Spiral Springs in the lathe	MEASURING TOOLS.
Hand Turning 330	End Measurements of large lathe work 370
The heel tool	Template gauges for
The graver and its applications 330, 331	Trammels or Trains
Hand side tools	Adjustable gauges for
Hand finishing tool	Compasses—Dividers
Hand Tools, for roughing out brass work	Compass calipers. 378 Key Seating rule. 378
Various forms and applications of scrapers 332, 333	Surface Gauge 378
Clockmakers' hand tool for special or standard work 334	Pattern makers' pipe gauge
Screw cutting with hand tools	Squares. The try square
Outside and inside chasers	The T square
Hobs and their uses	Varoius methods of testing squares
The application of chasers, and errors that may arise	Bevel squares
from the position in which they are presented to	Bevel Protractors
the work	Hexagon Gauge
V-tool for starting outside threads	Straight Edge and its applications
Starting outside threads	Surface Plate or planimeter
Cutting taper threads	Templates for curves
Wood turning hand tools	Wire Gauges, notch
The gauge and how to use it	Standard gauges for wire, &c
The chisel and its use	Gauge for music wire
The skew chisel and how to use it	Brown and Sharpe wire gauge
Wood turners' boring tools for lathe work 340	Birmingham wire gauge for rolled shell silver and gold 387
	Sheet iron gauge, Russian
CHAPTER XIV.	Galvanized iron
	Belgian sheet zinc 38 American sheet zinc 38
MEASURING MACHINES, TOOLS AND DEVICES.	Rifle Bore gauge
The state of the s	Strength of Wire, Kirkaldy's experiments 387, 388
Standards of Measurements, in various countries 341	
Use of, by sight and by the sense of feeling 341	CHAPTER XVI.
Variations in standard gauges 341	
The necessity for accurate standards	SHAPING AND PLANING MACHINES.
The Rogers Bond standard measuring machine 342	
Details of construction of	General description of a shaping machine
The principle of construction of	Construction of swivel head 386 Slide 390
The Whitworth measuring machine	Vice chuck
The Betts Machine Company's measuring machine 346	Feed motion 390
Professor Sweet's measuring machine	Hand shaping machine
Measuring machine for sheet metal	Quick Return Motion, Whitworth's
Circle, division of the	Vice Chucks, the principles of construction of plain, for planing
Troughton's method of dividing the circle 348, 349	machine
Ramsden's dividing engine	The proper methods of chucking work in
Pratt and Whitney's dividing device	Holding taper work in
Practical application of	Swiveling
Index wheel, method of originating, by R. Hoe & Co 353	Rapid motion
Application of the index wheel (Hoe & Co's system). 353	For vice work
Classification of the measuring tools used by workmen 354	Centres for shaping machines
Micrometer Caliper and its principle of construction 354, 355	Traveling Head in shaping machine
Gauges. Standard plug and collar gauges	Planer Shapers or shaping machines, having a tappet motion for
Methods of comparing standard plug and collar gauges 356 The effects of variations of temperature upon standard gauges 356	reversing the direction of motion
Plug and collar gauges for taper work	Quick Return Motion shaping machines, link 390 The Whitworth 400
The Baldwin standards for taper bolts	Comparisons of the link motion and Whitworth400
Workmen's gauges for lathe work 350	Simple Crank, investigating the motion of
Calipers, outside, the various forms of	Planing Machines, or planer
Inside calipers 360	The various motions of
Calipers with locking devices	The table driving gear402
Spring calipers	Planing machine with double heads402
The methods of holding and using	Rotary planing machine 405
Keyway calipers	CITA DOTTED AZIZZA
The advantages of calipers	CHAPTER XVII.
The influence of the diameter of the work in limiting the	DI ANINC MACHINEDY
application of standard gauges	PLANING MACHINERY.
The wear of tools and its influence upon the application	The Sellers planing machine 406
of the standard gauge system	The belt shifting mechanism
The influence of the smoothness of the surface upon the al-	The automatic feed motions 408
lowance to be made for drilling or hydraulic fits 365	Sliding Head
Examples of allowance for hydraulic fits 365	Cross Bar

Wear of the Slides of planer heads, various methods of taking up		PAGE
the	Stocks and Cutters. Adjustable stock and cutter	.448
Swivel Heads	Counterbores for drilling machines	110
Tool Aprons411	Drill and counterbore for wood work	440
Swivel Tool-holding devices for planers	Facing and countersink cutters	440
Planer Heads, graduations of 412 Safety devices for 413	Device for drilling square holes	450
Feed motions for	Device for drilling taper holes in a drilling machine	451
V-guideways for	GIVA DEPOSIT	
Flat guideways for 415	CHAPTER XX.	
Oiling devices for	HAND-DRILLING AND BORING TOOLS, AND	
Planing Machine Tables	DEVICES.	
Forms of bolts for planer tables		
Supplementary tables for planer tables	The Brad-awl Bits. The gimlet bit	452
Angle plates for planer tables	The German bit	454
Chucking devices for planer tables	The nail bit	452
Planer Centres 418 Planer Chucks 419	The spoon bit	452
For spiral grooved work	The nose bit	453
For curved work	The auger bitCook's auger bit	453
Chucking machine beds on planer tables	Principles governing the shapes of the cutting edges of auger	453
For large planing machines422	bits	453
Chucking the halves of large pulleys on a planer 423	Auger bit for boring end grain wood	453
Gauges for planing V-guideways in machine beds 421 Planing guideways in machine beds 422	The centre bit	454
Gauge for planer tools	The expanding bit. DrillsDrill for stone	454
Planer I ools, the shapes of	The fiddle drill	454
For coarse finishing feeds424	The fiddle drill with feeding device	455
The clearance of	Drill with cord and spring motion	455
For slotted work. 424 Planer Tool Holder, with tool post 425	Drill stock with spiral grooves	455
Various applications of	Drill brace Drill brace with ratchet motion	455
Simple and advantageous form of	Universal joint for drill brace	450
Examples of application of 426	Drill brace with multiplying gear and ratchet motion	456
	Breast drill with double gear	156
CHAPTER XVIII.	Drilling levers for blacksmiths	157
DDILL ING MAGUINES	Drill cranks.	457
DRILLING MACHINES.	Ratchet braceFlexible shaft for driving drills	457
Drilling Machines. General description of a power drilling	Drilling device for lock work	450
machine 428	Hand drilling machine	450
Lever feed	Slotting Machine	459
With automatic and quick return feed motions	Sectional view of	400
Improved, with simple belt and uniform motion, two series	Tool holders460.	461
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Sectional view of	461
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	461
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	461 462
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle. 434	Tool holders	461 462
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	461 462
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	461 462 NG
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle. 434 Four-spindle. 434 Four-spindle. 434 Combine of 431 Feed motion of 432 Combined Drilling Machine and lathe. 433 Combined Drilling Machine and lathe. 430 Combined Drilling Machine and	Tool holders	461 462 NG
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle. 434 Four-spindle. 434 Four-spindle. 434 Four-spindle. 434 Four-spindle. 434 Four-spindle. 431 Feed motion of. 432 Combined Drilling Machine and lathe. 433 Boring Machine, horizontal. 433	Tool holders	461 462 NG 463 463
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle. 434 Four-spindle. 434 Four-spindle. 434 Four-spindle. 431 Feed motion of. 432 Combined Drilling Machine and lathe. 433 Boring Machine, horizontal. 433 For car wheels. 438	Tool holders	461 462 NG 463 463 464
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle. 434 Four-spindle. 434 Drilling and Boring machine. 431 Feed motion of. 432 Combined Drilling Machine and lathe. 433 Boring Machine, horizontal. 433 For car wheels 438 For pulleys 438	Tool holders	461 462 NG 463 463 464 464
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle. 434 Four-spindle. 434 Four-spindle. 434 Feur-spindle. 435 Combined Drilling Machine and lathe. 437 Feed motion of. 432 Combined Drilling Machine and lathe. 433 Boring Machine, horizontal. 433 For car wheels 438 For pulleys. 438 Ouartering Machine. 438 Ouartering Machine.	Tool holders	461 462 NG 463 463 464 465 465
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle. 434 Four-spindle. 434 Drilling and Boring machine. 431 Feed motion of. 432 Combined Drilling Machine and lathe. 433 Boring Machine, horizontal. 433 For car wheels 438 For pulleys 438	Tool holders	461 463 463 463 464 465 466 466
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 420, 430 Radial	Tool holders	461 462 NG 463 463 464 465 466 466 466
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 436 Cotter or keyway. 438 434 Drilling Machine, three-spindle. 434 434 Four-spindle. 434 434 Drilling and Boring machine. 431 432 Combined Drilling Machine and lathe. 433 433 Boring Machine, horizontal. 433 433 For car wheels 438 438 For pulleys. 438 438 Quartering Machine. 434 435 Drilling and Turning Machine for boiler makers. 435	Tool holders	461 462 NG 463 463 464 465 466 466 466 466
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle 434 Four-spindle 434 Four-spindle 434 Prilling and Boring machine 431 Feed motion of 432 Combined Drilling Machine and lathe 433 Boring Machine, horizontal 433 For car wheels 438 For pulleys 438 Quartering Machine 434 Drilling and Turning Machine for boiler makers 435 Feed motions of 436 CHAPTER XIX.	Tool holders	461 462 NG 463 463 463 464 465 466 466 467 467
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 420, 430 Radial	Tool holders	461 462 NG 463 463 464 465 466 466 466 467 467
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	461 462 NG 463 463 463 464 465 466 466 467 467 468 468
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle 434 Four-spindle. 434 Four-spindle. 431 Feed motion of 432 Combined Drilling Machine and lathe 433 Boring Machine, horizontal 433 For car wheels 438 For pulleys 438 For pulleys 438 Quartering Machine Drilling Machine for boiler makers 435 Feed motions of 436 CHAPTER XIX. DRILLS AND CUTTERS FOR DRILLING MACHINES. Jigs or Fixtures for drilling machines 439 Limits of error in 439	Tool holders	461 462 NG 463 463 464 465 466 466 467 467 467 468 468 468 470
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	461 462 463 463 463 464 465 466 466 467 467 467 468 470 470
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	461 462 463 463 463 464 465 466 466 467 467 467 468 470 470
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle 434 Four-spindle 434 Four-spindle 434 Four-spindle 435 Feed motion of 432 Combined Drilling Machine and lathe 433 Boring Machine, horizontal 433 For car wheels 438 For pulleys 438 For pulleys 438 Quartering Machine Machine for boiler makers 435 Feed motions of 436 CHAPTER XIX. DRILLS AND CUTTERS FOR DRILLING MACHINES. Jigs or Fixtures for drilling machines 439 Limits of error in 439 Examples of, for simple work, as for links, &c. 440 Considerations in designing 440 For drilling engine cylinders. 441 For cutting out steam ports 441	Tool holders	461 462 NG 463 463 463 464 465 466 467 467 468 470 471
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle 434 Four-spindle 434 Four-spindle. 434 Four-spindle 434 Four-spindle 435 Feed motion of 432 Combined Drilling Machine and lathe 433 Boring Machine, horizontal 433 For car wheels 438 For pulleys 438 For pulleys 438 Quartering Machine Machine for boiler makers 435 Feed motions of 436 CHAPTER XIX. DRILLS AND CUTTERS FOR DRILLING MACHINES. Jigs or Fixtures for drilling machines 439 Limits of error in 439 Examples of, for simple work, as for links, &c. 440 Considerations in designing 440 For drilling engine cylinders. 441 Drills and Cutters for drilling machines 442	Tool holders	461 462 NG 463 463 463 464 465 466 466 467 467 472 472
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 420, 430 Radial	Tool holders	461 462 463 463 463 464 465 466 466 467 467 471 472 472 473
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	461 462 NG 463 463 463 464 465 466 466 467 470 471 472 472 473
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 420, 430 Radial	Tool holders	NG 463 463 463 463 465 466 466 467 467 472 472 472 473 473 473 473
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tools	NG 463463464654666467467474747347347347347474
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	461 462 NG 463 463 463 464 465 466 466 466 467 471 472 473 473 474 474 474
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	461 462 NG 463 463 463 464 465 466 466 466 467 471 472 473 473 474 474 474 474 475
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle 434 Four-spindle 434 Four-spindle 434 Four-spindle 434 Four-spindle 435 Feed motion of 432 Combined Drilling Machine and lathe 433 Boring Machine, horizontal 433 For car wheels 570 For car wheels 438 For pulleys 438 Guartering Machine Machine for boiler makers 435 Feed motions of 436 CHAPTER XIX. DRILLS AND CUTTERS FOR DRILLING MACHINES. Jigs or Fixtures for drilling machines 439 Limits of error in 439 Examples of, for simple work, as for links, &c. 440 Considerations in designing 440 For drilling engine cylinders 440 to 441 For cutting out steam ports 441 Drills and Cutters for drilling machines 442 Flat drills for drilling machines 442 Flat drills for drilling machines 442 Flat drills for drilling machines 442 Errors in grinding flat drills 443 The lip drill 443 Cotter or keyway drills. 444 Drilling hard metal. 444 Drilling hard metal. 444 Drilling hard metal. 444 Drilling hard metal. 444	Tool holders	461 462 NG 463 463 464 465 466 467 467 472 473 473 474 474 474 474 475
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	461462 NG 4634634644664664664664664664664664664664
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	4614664664664664664664664664664664664664
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	4614 462 NG 463463464666466646664666466646664666466
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial. 430, 431 For boiler shells. 430, 431 For boiler shells. 436 Cotter or keyway. 438 Drilling Machine, three-spindle. 434 Four-spindle. 434 Four-spindle. 434 Four-spindle. 434 Four-spindle. 435 Four-spindle. 437 Feed motion of. 432 Combined Drilling Machine and lathe. 433 Boring Machine, horizontal. 433 For car wheels 438 For pulleys. 438 Guartering Machine. 434 Drilling and Turning Machine for boiler makers. 435 Feed motions of. 436 CHAPTER XIX. DRILLS AND CUTTERS FOR DRILLING MACHINES. Jigs or Fixtures for drilling machines. 439 Limits of error in. 439 Examples of, for simple work, as for links, &c. 440 Considerations in designing. 440 For drilling engine cylinders. 441 For cutting out steam ports 441 Table of sizes of twist drills, and their shanks. 442 Flat drills for drilling machines. 442 Errors in grinding flat drills. 443 The lit-drill. 443 The lip drill. 443 The lip drill Cotter or keyway drills. 446 Drilling hard metal. 444 Table of sizes of tapping holes. 445 Drilli Shanks and sockets. 446 Square shanked drills and their disadvantages. 446 Drill Chucks. 446	Tool holders	NG 4634646466466466466466466466466466466466
Improved, with simple belt and uniform motion, two series of rates of automatic feed, and guide for boring bar. 429, 430 Radial	Tool holders	461462 NG 463464464646464646464646464646464646464

FULL-PAGE PLATES.

VOLUME I.

	Facing
Frontispiece.	MODERN LOCOMOTIVE ENGINE
PLATE I.	TEMPLATE-CUTTING MACHINES FOR GEAR TEETH
" II.	FORMS OF SCREW THREADS
" III.	MEASURING AND GAUGING SCREW THREADS
" IV.	END-ADJUSTMENT AND LOCKING DEVICES
" v.	EXAMPLES IN LATHE CONSTRUCTION
" VI.	CHUCKING LATHES
" VII.	TOOL-HOLDING AND ADJUSTING APPLIANCES
" VIII.	WATCHMAKER'S LATHE
" IX.	DETAILS OF WATCHMAKER'S LATHE
" X.	EXAMPLES OF SCREW MACHINES
" XI.	ROLL-TURNING LATHE
" XII.	EXAMPLES IN ANGLE-PLATE CHUCKING
" XIII.	METHODS OF BALL-TURNING
" XIV.	STANDARD MEASURING MACHINES
" XV.	DIVIDING ENGINE AND MICROMETER
" XVI.	SHAPING MACHINES AND TABLE-SWIVELING DEVICES
" XVII.	EXAMPLES OF PLANING MACHINES
" XVIII.	EXAMPLES IN PLANING WORK
" XIX.	LIGHT DRILLING MACHINES
" XX.	HEAVY DRILLING MACHINES
" XXI.	EXAMPLES IN BORING MACHINERY
" XXII.	BOILER-DRILLING MACHINERY
"XXIII.	NUT-TAPPING MACHINERY