



1 SUPPORT ROD
A.S.
2 REQ'D.


TOTAL LENGTH MUST BE MEASURED TO FIT YOUR MILLING MACHINE. SEE INSTRUCTIONS TO DETERMINE LENGTH.



15 CAP
COPPER
2 REQ'D



8 VALVE LEVER
ALUMINUM
1 REQ'D.



12 COMPRESSION FITTING
BRASS
4 REQ'D



14 .125 NPT
BRASS
PLUG FITTING
1 REQ'D.

WWW.HOMESHOPACCESSORIES.COM

MISCELLANEOUS PARTS

TITLE			
REV. 1	SHEET 1	SCALE 7/8=1	DATE 2/27/07
DWG NO			QUEST 7 OF 7